

Parish News Issue 49 Supplement



Jan and Ken discuss how much easier it is to Social Distance in an empty church



The organ has been carefully protected by the Organ Builder and his team



Ken explains how every last inch at the West End has been used to store the furniture



This piece of planking is from the ceiling of the box around the South door which they are presently taking down. It reads: "This screen was made and fixed November 1910 by W. Creed Maidenhead. F Townsend J Thame F Spackman F Singer (workmen)" So we know now exactly when it was built.



One of the Cliveden guys pointed out to Ken the name of Stevens on the ironwork on the dwarf wall. It appears again on the other side. I have no idea who Stevens was as the iron work is attributed to Leaver.



One can now see the step that was covered by the platform at the entrance to the chancel. Note the row of Minton tiles. These same tiles appear along both sides of the nave at roof level.



Considerable damage to the floor under the platform. In the photo on the left you can see a tile smashed into little pieces. It seems as though something very heavy was dropped on it as the floor is even indented at that point.